

Curriculum Vitae of the machine Reference number: 23516



Condition of the Machine:

Disclaimer:





BORGANA AG

SPECIAL OFFER

Production Year:	2010	More Details: small format cutter can also be connected behind a line V1 specifically it was connected behind the Horizon spf 200 4 knives + off-cut minimum cutting width 75 mm set of spare knives
Availability:	immediately	
Work Experiences:	folders from v1, separate sheets	
Sale Reason:	production reduction	

functional, condition and wear and tear according to its age, well maintained

not in daily production but can be seen running at your request

The Condition of the Machine assessment presented in this CV was either obtained from the last machine operator or is based on an inspection performed by our employee, just to provide you with as much information as

possible.

For more certainty we recommend your own check or an assessment of an independent mechanic. We cannot provide you with any machine guarantee.