

Curriculum Vitae of the machine Reference number: C 12536



POLYGRAPH 881-2-18 Gathering Machine

Production Year: 1980

More Details:

18 gathering stations with sucker feeding

Availability: immediately

Sale Reason: closing company



Condition of the Machine: functional, complete
not in daily production
but can be seen running
at your request

Disclaimer: The Condition of the Machine assessment presented in this CV was either obtained from the last machine operator or is based on an inspection performed by our employee, just to provide you with as much information as possible.
For more certainty we recommend your own check or an assessment of an independent mechanic. We cannot provide you with any machine guarantee.